



ISOMETRIC VIEW



PLAN



TRANSVERSE HEADER SECTION

NOTE: UPON COMPLETION OF FINAL SLAB, REMOVE DOWEL BARS AT SUCH TIME AS CONCRETE HAS CURED ENOUGH TO LEAVE A CAVITY FOR RESETTING AT A LATER DATE.

USE WOOD OR METAL FORM OF SUFFICIENT RIGIDITY TO ADEQUATELY SUPPORT THE EDGES OF THE SLAB.